

**U.S. ENVIRONMENTAL PROTECTION AGENCY  
REMOVAL ACTION**

**ADMINISTRATIVE RECORD  
FOR THE  
PILSEN SOILS RAILROAD AND ALLEY SITE  
OPERABLE UNIT 2  
CHICAGO, COOK COUNTY, ILLINOIS**

**ORIGINAL  
AUGUST 3, 2015  
SEMS ID: 919233**

<u>NO.</u>	<u>SEMS ID</u>	<u>DATE</u>	<u>AUTHOR</u>	<u>RECIPIENT</u>	<u>TITLE/DESCRIPTION</u>	<u>PAGES</u>
1	919188	Undated	H. Kramer & Co.	File	Brass & Bronze Ingots Nominal Composition Tables	6
2	919191	5/1/73	U.S. EPA	File	Air Pollution Engineering Manual - Chapter 6: Metallurgical Equipment	95
3	919192	1/1/86	Journal of Materials Science	File	Journal Article Abstract: "The Strength of Brass/Sn-Pb-Sb Solder Joints Containing 0 to 10% Sb"	1
4	918527	9/1/95	U.S. EPA Office of Compliance	File	Profile of the Nonferrous Metals Industry	138
5	919178	8/27/01	Pioneer Environmental	Retirement Program of Farley, Inc.	Site Investigation Report - Focused & Remediation Objectives Report for 900 W. 18th St. (Vol. I of II)	155
6	918533	1/1/03	USGS	File	Concentrations of Polynuclear Aromatic Hydrocarbons and Inorganic Constituents in Ambient Surface Soils, Chicago, Illinois: 2001-02	84
7	919190	8/1/03	U.S. EPA	File	Superfund Lead-Contaminated Residential Sites Handbook	124
8	919175	1/1/05	Chicago Department of Environment	File	Report Regarding H. Kramer and Company - 1345 West 21st St.	34

<b><u>NO.</u></b>	<b><u>SEMS ID</u></b>	<b><u>DATE</u></b>	<b><u>AUTHOR</u></b>	<b><u>RECIPIENT</u></b>	<b><u>TITLE/DESCRIPTION</u></b>	<b><u>PAGES</u></b>
9	919186	6/1/05	IEPA	Pilsen Environmental Rights and Reform Organization	Response to Pilsen Environmental Rights and Reform Organization Questions Regarding Operations at H. Kramer and Company	12
10	919176	9/1/07	Conestoga Rovers & Associates	IEPA	Updated Focused Site Investigation Report - H. Kramer	665
11	919179	8/31/11	Parker, D., U.S. EPA	Som, K., U.S. EPA	Technical Report on the Characterization of Lead-Bearing Particulate Matter in the Pilsen Neighborhood	25
12	915292	4/30/13	Weston Solutions	Mendoza, R., U.S. EPA	Field Sampling Plan (Revision 2)	236
13	915298	4/2/14	Weston Solutions, Inc.	U.S. EPA	Site Assessment Report (Revision 3)	433
14	919189	10/24/14	ASTM International	File	Standard Specification for White Metal Bearing Alloys (Known Commercially as "Babbitt Metal")	4
15	918526	10/27/14	Canar, J., Jacobsen, L, and Roth, C., U.S. EPA FIELDS Group	File	Report for the Statistical Analysis of Cadmium, Copper, Lead, Tin, and Zinc Found in Soil at and near the H. Kramer Facility	18
16	919183	11/17/14	Mehl, R., Weston	Mendoza, R., U.S. EPA	Removal Site Evaluation Report for Pilsen Soil Assessment Area: Residential (Redacted Version)	593
17	918530	2/6/15	National Enforcement Investigations Center	U.S. EPA	Final Technical Report on the Characterization of Lead in Soils, Pilsen Neighborhood	117
18	919187	3/26/15	Mendoza, R., U.S. EPA	Everetts, B., IEPA	Letter re: Request for ARARs at the Pilsen Soils Operable Unit 2 Residential Site	2
19	919181	5/6/15	Fusinski, K., U.S. EPA	Mendoza, R., U.S. EPA	Memo re: Risk Assessment for the Pilsen Smelter Site Residential Neighborhood Areas Res1 and Res2a	6
20	919185	6/4/15	U.S. EPA	File	Envirofacts TRI Search Results - Fisk Generating Station	10

<u>NO.</u>	<u>SEMS ID</u>	<u>DATE</u>	<u>AUTHOR</u>	<u>RECIPIENT</u>	<u>TITLE/DESCRIPTION</u>	<u>PAGES</u>
21	919180	7/8/15	Mendoza, R., U.S. EPA	Ribordy, M., U.S. EPA	Memo re: Definition of Operable Unit 2 Boundary for the Pilsen Soil Operable Unit 2 Residential Site	19
22	919231	8/3/15	Mendoza, R., U.S. EPA	Karl, R., U.S. EPA	Action Memorandum re: Request for Approval and Funding for a Time-Critical Removal Action at the Pilsen Soil Operable Unit 2 Railroad Spur and Alley Site <i>(Portions of this document have been redacted)</i>	37